


Processing Record for this file:  
(Make notes here unique for this file)

Loading 3/1 - 4/1/2014  
Data loaded directly from DMF


Processed SO<sub>2</sub> data normally. These data are taken with a ~10-s time constant on the instrument.

During the beginning of the month, the instrument flash lamp failed, at first intermittently and then completely. The data grew increasingly noisy. The ambient signal appeared near background when the instrument was functioning. No valid data reported after 2014-03-08 01:49 and several shorter period prior to this.


# TEI Model 43i-TLE Pulsed Fluorescence SO<sub>2</sub> Analyzer



TEI Model 43i-TLE Pulsed Fluorescence SO<sub>2</sub> Analyzer  
Housekeeping




## TEI Model 43i-TLE Pulsed Fluorescence SO<sub>2</sub> Analyzer Zero/Span Checks




Project/Platform/Site: maomaoscs1  
ARM Climate Research Facility  
Contact: S.R. Springston (631) 344-4477, srs@bnl.gov

Entire Period


# TEI Model 43i-TLE Pulsed Fluorescence SO<sub>2</sub> Analyzer



# TEI Model 43i-TLE Pulsed Fluorescence SO<sub>2</sub> Analyzer




# TEI Model 43i-TLE Pulsed Fluorescence SO<sub>2</sub> Analyzer



Project/Platform/Site: maomaoscs1  
ARM Climate Research Facility  
Contact: S.R. Springston (631) 344-4477, srs@bnl.gov


# TEI Model 43i-TLE Pulsed Fluorescence SO<sub>2</sub> Analyzer




Project/Platform/Site: maomaoscs1  
ARM Climate Research Facility  
Contact: S.R. Springston (631) 344-4477, srs@bnl.gov



# TEI Model 43i-TLE Pulsed Fluorescence SO<sub>2</sub> Analyzer



# TEI Model 43i-TLE Pulsed Fluorescence SO<sub>2</sub> Analyzer



Project/Platform/Site: maomaoscs1  
ARM Climate Research Facility  
Contact: S.R. Springston (631) 344-4477, srs@bnl.gov