

Processing Record for this file:
(Make notes here unique for this file)

Loading 2015-03-01 - 2015-04-01


Data loaded from DMF. Files detarred, unzipped and names restored

Processed SO₂ data normally. These data are taken with a ~10-s time constant on the instrument.


Ambient data appear reliable. There is a time lag after the standard additions where a slight signal shows up as the calibration line flushes out.

This month showed another ~10% increase in S.A. response. Probably due to flow changes in the manifold. However, this could also be a lamp voltage issue.


TEI Model 43i-TLE Pulsed Fluorescence SO₂ Analyzer



TEI Model 43i-TLE Pulsed Fluorescence SO₂ Analyzer
Housekeeping




TEI Model 43i-TLE Pulsed Fluorescence SO₂ Analyzer
Zero/Span Checks




Entire Period


TEI Model 43i-TLE Pulsed Fluorescence SO₂ Analyzer




TEI Model 43i-TLE Pulsed Fluorescence SO₂ Analyzer




TEI Model 43i-TLE Pulsed Fluorescence SO₂ Analyzer



TEI Model 43i-TLE Pulsed Fluorescence SO₂ Analyzer



TEI Model 43i-TLE Pulsed Fluorescence SO₂ Analyzer



TEI Model 43i-TLE Pulsed Fluorescence SO₂ Analyzer

